


New calibration settings have been measured.
Tap the screen to register saved data.
Wait for 30 seconds to cancel saved data and keep the current setting.

Time limit : 29 sec



Update complete, thank you for the execution of the procedure